

Metropolitan Branch Trail Design Build, South Segment

DC CONTRACT NO. DCKA-2016-C-0044

FAP No.: STP-2016 (060)

CONSTRUCTION MANAGER'S WEEKLY PROGRESS REPORT

03/22/2020 - 03/28/2020

Project Website: <u>www.metbranchtrail-forttotten.com</u> For Additional Trail Information Please see <u>www.metbranchtrail.com</u>



Proposed Metropolitan Branch Trail





MBT DB, SOUTH SEGMENT CONSTRUCTION MANAGER'S WEEKLY PROGRESS REPORT WEEK ENDING 03/28/2020

1. PROJECT DESCRIPTION

The planned Metropolitan Branch Trail Project ("the Project") consists of the design and construction of a new trail adjacent to CSX tracks and WMATA Red Line tracks along John McCormack Drive, adjacent to Fort Totten Metro Station, and on NPS property in NE, Washington D.C. The trail begins approximately 1500 feet south of Bates Road NE on the east side of John McCormack Drive NE, extending north along the WMATA and CSX tracks to the Fort Totten Metro Station tie in with First Place NE. An existing trail connection from Gallatin Road NE to the Fort Totten Metro Station will be reconstructed as a part of the Project.

The Project is 83.15% Federally-Funded and 16.85% District-Funded. Potomac Construction is the Design Build contractor.

Delon Hampton and Associates Chartered is providing Construction Management and Inspection services.

Specific Construction Scope of Work includes:

- Existing street light poles from the beginning point of the project south to Michigan Avenue shall have the existing luminaires replaced with new LED cobra head luminaires, see Section 16 of the Project Technical Provisions for details;
- Provide mobilization and demobilization, provision and maintenance of Engineer's field facilities, field layout, employee training, and other incidental work required for a quality, complete and finished product;
- Establishment and maintenance of vehicular and pedestrian traffic including signs, barricades and other transition devices; reconfiguring the devices in conjunction with changes in work areas; and their removal and disposal upon project completion, including restoration of disturbed areas;
- Clearing and grubbing, as required within the LOD;
- Removal of unsuitable material, excavation, and backfilling and pervious paving to construct a new trail;
- Protection of trees during construction;
- Provide ADA compliant trail connections and pedestrian ramps;
- Provide retaining walls as necessary to stay within the LOD and minimize property impacts following visual requirements specified for retaining walls on NPS property;
- Provide new permanent regulatory and wayfinding signs for the trail and all trail connection intersections;
- Provide road and trail pavement markings;
- Provide landscaping within the LOD for the Project including special requirements for landscaping on NPS property;
- Provide erosion and sediment control measures, storm water management facilities, including pervious asphalt pavement and bioretention facilities;
- Provide utility coordination, identification, locating, and protection of all utilities encountered during design and construction including relocation of Pepco poles along Aggregate Industries property; and
- Provide new WMATA security fencing between the trail and CSXT tracks.
- Remove existing sidewalk and widen sidewalk to 10' along the west, side of First Place NE from Metropolitan Branch Trail to entrance to WMATA bus loop, on west side.





2. STATUS OF CONSTRUCTION / PROGRESS SUMMARY

Work performed this week:

Design

- Address comments on permit application from DCRA
- Resubmittal of Comment Matrix for Submittal D
- Resubmittal of Plans for Submittal D to DDOT and DC Water
- Obtain DC Water utility release letter
- Work on Permit applications for WMATA for Phase D

Construction:

Phase B

- Excavated, graded the trail's subgrade and placed stone.
- Installed perforated underdrain pipes.
- Installed light poles

Phase D

- Cut and removed trees within the limit of disturbance. Performed clearing and grubbing.
- CSX construction field inspector performed safety briefings
- Monitoring of Aggregate Industries water discharge

CM Consultant:

- Monitored construction progress, make sure all applicable inspection and testing were performed.
- Attended Design Coordination Meeting conference call.
- Attended QA/QC meeting conference call.
- Reviewed updated schedule that has been submitted by Potomac on 02/26/20.
- Reviewed invoice No. 14.
- Reviewed Inspection Daily Reports.

3. MEETINGS / PROJECT COORDINATION

Mon	03/22/20	DDOT/QA Meeting conference call for asphalt paving and safety briefing held at 10:00 A.M.
Mon	03/23/20	DDOT, PCCI and Aggregate Industries safety briefing meeting was held at Aggregate Industries at 7:30 A.M.
Tues. Fri.	03/24/20 03/20/20	Design Coordination Meeting conference call was held at 10:00 A.M. QA/QC Meeting conference call was held at 10:00 A.M.

4. DAILY WORK PERFORMED

Sun	03/22/20	No work performed
Mon	03/23/20	No work performed due to rain





MBT DB, SOUTH SEGMENT CONSTRUCTION MANAGER'S WEEKLY PROGRESS REPORT

WEEK ENDING 03/28/2020

Infiltration facility Material Testing

Tue	03/24/20	Phase B - Excavated, stone placing and grading. Installed perforated Underdrain pipes for the proposed trail. Phase B - Electrical Work - Installed light poles Phase D – Cut the trees, performed clearing and grubbing
Wed	03/25/20	No work performed due to rain
Thurs	03/26/20	Phase B – Stone placing and grading
		Phase D – Cut the trees, performed clearing and grubbing
Fri	03/27/20	Phase B – Stone placing and grading
	03/27/20	Phase D – Cut the trees, performed clearing and grubbing
Sat	03/28/20	No work scheduled

7. **INSPECTION & MATERIAL TESTS PERFORMED**

- \boxtimes Jobsite Safety Inspection
- \square **Erosion and Sediment Control** inspection
 - MOT Inspection
 - **Compaction Test**
 - Asphalt Material Testing
 - Concrete Material Testing

DBE PARTICIPATION SUMMARIES 10.

Potomac Construction (Contractor)

DBE Goal for Contractor is 15%. To-date the Contractor has achieved 36% of their goal. •

Delon Hampton & Associates (CM)

• DBE Goal for the CM is 10%. To-date the CM has achieved 0% of their Goal.

ACCIDENTS / INCIDENTS 11.

None occurred on-site.





MBT DB, SOUTH SEGMENT CONSTRUCTION MANAGER'S WEEKLY PROGRESS REPORT WEEK ENDING 03/28/2020

12. PHOTOS OF THE WORK PERFORMED



Phase B – Crew installing 4" underdrain pipes for the proposed trail



Phase B – Crew placing and grading stone at the proposed trail







Phase B – Light Pole installation



Phase B – Crew compacting the installed stone





MBT DB, SOUTH SEGMENT CONSTRUCTION MANAGER'S WEEKLY PROGRESS REPORT

WEEK ENDING 03/28/2020



Phase D – Crew cutting the trees



Phase D – Crew cutting the trees





MBT DB, SOUTH SEGMENT CONSTRUCTION MANAGER'S WEEKLY PROGRESS REPORT WEEK ENDING 03/28/2020



Phase D – Crew cutting the trees



Phase D – Crew cutting trees

