



# Speed Limit and Safety Nexus Studies for Automated Enforcement Locations in the District of Columbia 5700 Block MacArthur Boulevard NW S/B

Study	Area	and Loo	cation		
District	PSA	Ward	ANC	Phase	Description
2	205	3	3D	Planned	5700 Block MacArthur Boulevard Northwest Southbound



This *planned* speed camera is located in Ward 3 at the 5700 block of MacArthur Boulevard Northwest in the southbound direction. MacArthur Boulevard runs parallel to the Potomac River from Maryland in the north to Canal Road Northwest in the south. The posted speed limit is 25 MPH.







### Field Assessment Summary

MacArthur Boulevard is assumed to run in the North-South direction, and is classified as a principal arterial. MacArthur Boulevard has two lanes in each direction. This site has the following characteristics:

- Located in a residential area with apartment buildings, houses, and driveways on both sides of the • street.
- The Capital Crescent Trail and Chesapeake & Ohio Trail both run parallel to MacArthur Boulevard 0.15 • miles to the west.
- Sibley Memorial Hospital is in the area.
- There is on street parking and sidewalks with curb and gutter on both sides of the street, as well as a center grass median in the middle of the street.
- There are bus stops on southwest and northeast corners as well as others in the area.
- The existing pavement is in fair condition.



Looking Northbound







# Speed Data Analysis

Posted Speed Limit (MPH)	25
Mean Speed (MPH)	25
85th Percentile Speed (MPH)	29
10 MPH Pace Speed	21-30
ADT	7,750

The 85<sup>th</sup> percentile speed is 4 MPH higher than the posted speed limit and the mean speed is the same as the posted speed limit.

# Crash Data Analysis


From the Accident Summary Report provided for the dates between January 1, 2010 and December 31, 2012, there were a total of four crashes at this location. A breakdown of collision type can be found in the chart on the next page.

The most common type of crash at this location was Side Swiped (2 crashes). There was also one Rear End and one Right Angle collision.





Severity			Weather			Surface	condit	ion	Light Condition			
Total	4											
Fatal	0	0.0%	Clear	2	50.0%	Dry	2	50.0%	Day	3	75.0%	
Injury	2	50.0%	Rain	2	50.0%	Wet	2	50.0%	Night	1	25.0%	
Truck	1	25.0%	Snow	0	0.0%	Snow/Ice	0	0.0%				
Police/EMS	1	25.0%										



## Safety Nexus

This site presents the following safety considerations, which may establish a nexus between the speed camera and traffic safety:

- 1. Speed Data The speed data analysis shows the 85<sup>th</sup> percentile speed higher than the posted speed limit.
- 2. Crash Data There was a low number of crashes recorded at this location.
- 3. Field Assessment The following site characteristics suggest a need for a safer travel environment:
  - a. Located in a residential area with apartment buildings, houses, and driveways on both sides of the street.
  - b. The Capital Crescent Trail and Chesapeake & Ohio Trail both run parallel to MacArthur Boulevard 0.15 miles to the west which generates pedestrian activity.
  - c. There is on-street parking at this location.
  - d. There are multiple bus stops in the area which generate pedestrian activity.





Due to the 85<sup>th</sup> percentile speeds, and the specific site characteristics of a residential area and pedestrian generators, there is a nexus between traffic safety and the speed camera at this location.

# SAMMAT ENGINEERING SERVICES, LLC

#### 1515 RISING RIDGE ROAD MOUNT AIRY, MD 21771

### www.sammateng.com

### 5700 block of MacArthur Blvd NW NB Speed

NB															
Start	1	16	21	26	31	36	41	46	51	56	61	66	71	76	
Time	15	20	25	30	35	40	45	50	55	60	65	70	75	999	Total
11/06/13	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
01:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
02:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
03:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
04:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
05:00	0	3	49	46	16	2	0	0	0	0	0	0	0	0	116
06:00	12	11	148	140	34	2	0	0	0	0	0	0	0	0	347
07:00	19	43	271	262	43	3	1	0	0	0	0	0	0	0	642
08:00	33	51	357	292	44	3	1	0	0	0	0	0	0	0	781
09:00	17	18	249	261	51	5	1	0	0	0	0	0	0	0	602
10:00	4	22	135	141	47	5	0	0	0	0	0	0	0	0	354
11:00	9	21	141	158	40	6	1	0	0	0	0	0	0	0	376
12 PM	9	18	112	173	44	6	0	0	0	0	0	0	0	0	362
13:00	3	21	158	152	27	6	1	0	0	0	0	0	0	0	368
14:00	10	18	171	186	40	2	0	0	0	0	0	0	0	0	427
15:00	5	13	177	255	68	4	0	0	0	0	0	0	0	0	522
16:00	9	17	207	271	57	6	0	0	0	0	0	0	0	0	567
17:00	11	29	271	280	32	3	0	0	0	0	0	0	0	0	626
18:00	13	18	253	246	40	2	0	0	0	0	0	0	0	0	572
19:00	11	34	221	134	14	2	0	0	0	0	0	0	0	0	416
20:00	2	15	108	114	22	0	0	0	0	0	0	0	0	0	261
21:00	5	9	71	63	12	0	1	0	0	0	0	0	0	0	161
22:00	0	5	63	55	12	0	0	0	0	0	0	0	0	0	135
23:00	2	2	15	24	9	1	0	0	0	0	0	0	0	0	53
Total	174	368	3177	3253	652	58	6	0	0	0	0	0	0	0	7688

# SAMMAT ENGINEERING SERVICES, LLC

#### 1515 RISING RIDGE ROAD MOUNT AIRY, MD 21771

### www.sammateng.com

### 5700 block of MacArthur Blvd NW NB Speed

NB															
Start	1	16	21	26	31	36	41	46	51	56	61	66	71	76	
Time	15	20	25	30	35	40	45	50	55	60	65	70	75	999	Total
11/07/13	0	1	8	4	4	1	0	0	0	0	0	0	0	0	18
01:00	0	1	2	1	2	0	0	0	0	0	0	0	0	0	6
02:00	0	1	2	1	0	0	0	0	0	0	0	0	0	0	4
03:00	0	1	2	1	3	0	0	0	0	1	0	0	0	0	8
04:00	0	1	12	10	2	1	0	0	0	0	0	0	0	0	26
05:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
06:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
07:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
08:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
09:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
10:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
11:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
12 PM	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
13:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
14:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
15:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
16:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
17:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
18:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
19:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
20:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
21:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
22:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
23:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
Total	0	5	26	17	11	2	0	0	0	1	0	0	0	0	62
Grand Total	174	373	3203	3270	663	60	6	0	0	1	0	0	0	0	7750
			50th I 85th I 95th I	Percentile : Percentile : Percentile : Percentile :		19 MPH 24 MPH 29 MPH 32 MPH									
Stats			ean Speed		21-	25 MPH 30 MPH									

10 MPH Pace Speed :	21-30 MPH
Number in Pace :	5586
Percent in Pace :	72.1%
Number of Vehicles > 25 MPH :	3831
Percent of Vehicles > 25 MPH :	49.4%

# SAMMAT ENGINEERING SERVICES, LLC

1515 RISING RIDGE ROAD MOUNT AIRY, MD 21771

### www.sammateng.com

### 5700 block of MacArthur Blvd NW NB Volume

Start	Wed	06-Nov-13	Thu	07-Nov-13	Fri	08-Nov-13	Daily Av	/erage
Гime	A.M.	P.M.	A.M.	P.M.	A.M.	P.M.	A.M.	P.M.
12:00	*	100	7	*	*	*	7	1
12:15	*	74	7	*	*	*	7	
12:30	*	88	2	*	*	*		
12:45	*	100	2	*	*	*	2 2	1
01:00	*	89	2	*	*	*	2	
01.00	*	89	2	*	*	*	2 2	
01:15	*	89		*	*	*		
01:30	*	92	1	*	*	*	1	
01:45		98	1		*	*	1	
02:00	*	85	1	*	*	*	1	
02:15	*	88	2	*			2	
02:30	*	121	0	*	*	*	0	1
02:45	*	133	1	*	*	*	1	1
03:00	*	135	2	*	*	*	2 2	1
03:15	*	130	2	*	*	*	2	1
03:30	*	127	2	*	*	*	2	1
03:45	*	130	2 2	*	*	*	2 2	1
04:00	*	136	5	*	*	*	5	1
04:15	*	142	4	*	*	*	4	1
04:30	*	146	8	*	*	*		1
04.30	*		9	*	*	*	8	
04:45		143	*	*	*	*	9	1
05:00	16	147	*				16	1
05:15	27	156	*	*	*	*	27	1
05:30	26	154	*	*	*	*	26	1
05:45	47	169	*	*	*	*	47	1
06:00	46	133	*	*	*	*	46	1
06:15	71	151	*	*	*	*	71	1
06:30	104	141	*	*	*	*	104	1
06:45	126	147	*	*	*	*	126	1
07:00	121	105	*	*	*	*	121	1
07:15	153	129	*	*	*	*	153	1
07:30	172	107	*	*	*	*	172	
07.30	172	107	*	*	*	*	172	1
07:45	196	75	*	*	*	*	196	
08:00	155	74		*	*	*	155	
08:15	209	59	*				209	
08:30	217	66	*	*	*	*	217	
08:45	200	62	*	*	*	*	200	
09:00	168	44	*	*	*	*	168	
09:15	154	42	*	*	*	*	154	
09:30	140	30	*	*	*	*	140	
09:45	140	45	*	*	*	*	140	
10:00	115	41	*	*	*	*	115	
10:15	92	35	*	*	*	*	92	
10:30	92	32	*	*	*	*		
	66	27	*	*	*	*	66	
10:45	81					+	81	
11:00	92	25	*	*	*	*	92	
11:15	92	10	*	*	*	*	92	
11:30	97	7	*	*	*	*	97	
11:45	95	11	*	*	*	*	95	
Total	3218	4470	62	0	0	0	3280	44
Combined				<b>`</b>				
Total	76	88	6	2	C	J	7750	
Peak	08:15	05:00	04:00				08:15	05:
Vol.	794	626	26				794	6
P.H.F.	0.915	0.926	0.722				0.915	0.9
Г.П.Г.	0.913	0.920	11///				0 9 10	0.9

### DC Department of Transportation - Traffic Accident Reporting and Analysis System

# Accident Summary Report (R-8)

	HUR BLVD,NW F From 01/01/2010		VARK ST,NW TO		/IB ST,NW Rahul Jain	Prepared Da	te.	9/15/2013
Total Number of Accident:		4	Collision Type	#ACC		Collision Type	#AC	
Total Number of Fatalities		0	Right Angle:	1		Fixed Object:	0	0.0%
Total Number of Injuries:		4	Left Turn:	0		Ran Off Road:	0	0.0%
Total Number of Disabling	Injurios:	1	Right Turn:	0		Ped. Involved:	0	0.0%
Total Number of NonDisat		1	Rear End:	1		Backing:	0	0.0%
Total Number of Pedestria		0	Side Swiped:	2		Non Collision:	0	0.0%
Total Number of Bicycles		0	Head On:	0		Under/Over Ride:	-	0.0%
Total Number of Motorcyc		0	Parked:	0		Unspecified:	0	0.0%
Time of Day	#ACC	%			Day o fweek	#AC	с	%
07:30 ~ 09:30:	1	25.0%			Sunday:	0	-	0.0%
09:30 ~ 11:30:	0	0.0%			Monday:	2		50.0%
11:30 ~ 13:30:	1	25.0%			Tuesday:	0		0.0%
13:30 ~ 16:00:	1	25.0%			Wednesday:	2		50.0%
16:00 ~18:30:	0	0.0%			Thursday:	0		0.0%
18:30 ~ 07:30:	1	25.0%			Friday:	0		0.0%
Unspecified:	0	0.0%			Saturday:	0		0.0%
Weather Condition	#ACC	%			Surface Condition	#AC	с	%
Clear:	2	50.0%			Dry:	2		50.0%
Rain:	2	50.0%			Wet:	2		50.0%
Snow:	0	0.0%			Snow/Ice:	0		0.0%
Sleet/Hail:	0	0.0%			Slush:	0		0.0%
Fog/Mist:	0	0.0%			Water/Sand:	0		0.0%
Crosswind/Blowing Sand:	0	0.0%			Repairing:	0		0.0%
Unspecified:	0	0.0%			Unspecified:	0		0.0%
Type of Vehicle	#VEH	%			Accident Severity	Type #AC	с	%
Passenger Car:	8	80.0%			Fatal Collision:	0		0.0%
Bus:	0	0.0%			Injury Collision:	2		50.0%
Truck:	1	10.0%			PDO Collision:	2		50.0%
Taxi:	0	0.0%					_	
Minivan:	0	0.0%			Light Condition	#AC	C	% 75.00/
Police/Emergency Vehicle	: 1	10.0%			Daylight:	3		75.0%
Motorcycle/Moped:	0	0.0%			Dawn/Dusk:	0		0.0%
Bicycle:	0	0.0%			Dark(Lighted):	1		25.0%
Fixed Object:	0	0.0%			Dark(Not Lighted):	0		0.0%
Unspecified:	0	0.0%			Dark(Unknown Ligh Unspecified:	nting): 0 0		0.0% 0.0%
Contributing Factor	#VEH	%			Podostrian Action	s #AC	<u> </u>	%
•	# <b>VEH</b> 0	%0.0			Pedestrian Action		0	% 0.0%
Driver: Speed:						0		
Driver: Alcohol/Drug: Driver: Electronic Device:	0	0.0%			In Crosswalk agains	•		0.0%
	0	0.0%			In Crosswalk no Sig			0.0%
Driver: Others:	1	10.0%			In Unmarked Cross			0.0%
Vehicle:	0	0.0%			Not in Crosswalk:	0		0.0%
Roadway:	0	0.0%			From Between Park			0.0%
Unspecified:	9	90.0%			Unspecified:	0		0.0%

2 Records are not approved as of 9/15/2013 12:09:51 PM