



Speed Limit and Safety Nexus Studies for Automated Enforcement Locations in the District of Columbia 300 Block Rock Creek Church Road NW

Study Area and Location

District	PSA	Ward	ANC	Phase	Description
4	407	4	4C	Proposed	300 Block Rock Creek Church Road Northwest
					Southwestbound



The *proposed* speed camera will be located in Ward 4 at the 300 block of Rock Creek Church Road Northwest in the southwestbound direction. Rock Creek Church Road Northwest runs between North Capitol Street Northeast to the northeast and Georgia Avenue Northwest to the southwest. The posted speed limit is 25 MPH.





Field Assessment Summary

Rock Creek Church Road Northwest is assumed to run in a northeast-southwest direction, and is classified as a collector road. Rock Creek Church Road has one travel lane in each direction. This site has the following characteristics:

- This is a residential area with houses on the northwest side of the street.
- There is one school in the area: Preparatory School of DC.
- There are crosswalks at 4th Street and 3rd Street.
- There is sidewalk on both sides of the street and on-street parking on the west side of the street.
- There are rumble strips on the block.
- The pavement is in fair condition and there is curb and gutter with drainage inlets.
- There is a bus stop southbound at 4th Street and one northbound at 3rd Street.







Speed Data Analysis

Posted Speed Limit (MPH)	25
Mean Speed (MPH)	24
85th Percentile Speed (MPH)	29
10 MPH Pace Speed	21-30
ADT	1,587


The mean speed is lower than the posted speed limit by 1 MPH and the 85th percentile speed is higher than the posted speed by 4 MPH at this location.

Crash Data Analysis

From the Accident Summary Report provided for the dates between January 1, 2013 and December 31, 2013 there were a total of two crashes at this location. A breakdown of number of crashes by collision type can be found in the chart on the next page. The most common types of crashes at this location were Parked (1) and Backing (1).



	Severity			Weather	•	Surfa	ce cond	lition	Light Condition			
Total	2											
Fatal	0	0.0%	Clear	2	100.0%	Dry	2	100.0%	Day	1	50.0%	
Injury	0	0.0%	Rain	0	0.0%	Wet	0	0.0%	Night	1	50.0%	
Truck	0	0.0%	Snow	0	0.0%	Snow/Ice	0	0.0%				
Bus	0	0.0%										



Safety Nexus

This site presents the following safety considerations which may establish a nexus between traffic safety and the speed camera:

- 1. Speed Data The 85th percentile speed is higher than the posted speed limit at this location.
- 2. Crash Data The crash data analysis shows a low number of crashes at this location.
- 3. Field Assessment The following site characteristics suggest a need for a safer travel environment:
 - a. This is a residential area with houses on the northwest side of the street.
 - b. There is one school in the area: Preparatory School of DC.
 - c. There are multiple bus stops in the area which generate pedestrian activity.
 - d. There is on-street parking on the west side of the street.
 - e. There are rumble strips on the block which suggest a speeding issue.

Although the crash data analysis showed a low number of crashes at this location, the 85th percentile speed and the presences of rumble strips reveals an issue with speeding on the roadway. Due to the speed data

W4 - 287



analysis, the presence of rumble strips, the specific site characteristics of a residential area, and the pedestrian generators, there is a nexus between traffic safety and the speed camera at this location.

SAMMAT ENGINEERING SERVICES, LLC

1515 RISING RIDGE ROAD MOUNT AIRY, MD 21771

www.sammateng.com

300 Block of Rock Creek Church RD NW SWB Speed

SWB															
Start	1	16	21	26	31	36	41	46	51	56	61	66	71	76	
Time	15	20	25	30	35	40	45	50	55	60	65	70	75	999	Total
11/10/13	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
01:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
02:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
03:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
04:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
05:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
06:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
07:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
08:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
09:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
10:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
11:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
12 PM	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
13:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
14:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
15:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
16:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
17:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
18:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
19:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
20:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
21:00	*	*	*	*	*	*	*	*	*	*	*	*	*	*	*
22:00	4	3	13	6	0	0	0	0	0	0	0	0	0	0	26
23:00	2	3	12	15	3	0	0	0	0	0	0	0	0	0	35
Total	6	6	25	21	3	0	0	0	0	0	0	0	0	0	61

SAMMAT ENGINEERING SERVICES, LLC

1515 RISING RIDGE ROAD MOUNT AIRY, MD 21771

www.sammateng.com

300 Block of Rock Creek Church RD NW SWB Speed

SWB															
Start	1	16	21	26	31	36	41	46	51	56	61	66	71	76	
Time	15	20	25	30	35	40	45	50	55	60	65	70	75	999	Total
11/11/13	3	2	7	9	2	0	0	0	0	0	0	0	0	0	23
01:00	5	1	1	2	0	0	0	0	0	0	0	0	0	0	9
02:00	1	1	4	7	0	0	0	0	0	0	0	0	0	0	13
03:00	0	1	0	5	1	1	0	0	0	0	0	0	0	0	8
04:00	3	1	3	4	2	0	0	0	0	0	0	0	0	0	13
05:00	1	2	6	12	4	0	0	0	0	0	0	0	0	0	25
06:00	2	3	16	23	2	1	0	0	0	0	0	0	0	0	47
07:00	6	10	29	36	8	2	0	0	0	0	0	0	0	0	91
08:00	4	3	34	49	13	0	0	0	0	0	0	0	0	0	103
09:00	1	5	29	35	7	2	0	0	0	0	0	0	0	0	79
10:00	2	7	32	30	6	0	0	0	0	0	0	0	0	0	77
11:00	3	2	33	46	2	1	0	0	0	0	0	0	0	0	87
12 PM	3	4	36	55	10	0	0	0	0	0	0	0	0	0	108
13:00	4	2	40	38	4	1	0	0	0	0	0	0	0	0	89
14:00	3	9	25	47	22	0	0	0	0	0	0	0	0	0	106
15:00	2	8	50	53	14	0	0	0	0	0	0	0	0	0	127
16:00	3	9	53	46	3	2	0	0	0	0	0	0	0	0	116
17:00	1	7	52	34	5	2	0	0	0	0	0	0	0	0	101
18:00	6	15	48	33	5	1	0	0	0	0	0	0	0	0	108
19:00	4	3	33	36	4	0	1	0	0	0	0	0	0	0	81
20:00	0	4	18	22	8	0	0	0	0	0	0	0	0	0	52
21:00	0	9	18	15	4	1	0	0	0	0	0	0	0	0	47
22:00	0	8	5	2	0	1	0	0	0	0	0	0	0	0	16
23:00	0	0	0	0	0	0	0	0	0	0	0	0	0	0	0
Total	57	116	572	639	126	15	1	0	0	0	0	0	0	0	1526
Grand Total	63	122	597	660	129	15	1	0	0	0	0	0	0	0	1587

 15th Percentile:
 18 MPH

 50th Percentile:
 24 MPH

 85th Percentile:
 29 MPH

 95th Percentile:
 32 MPH

 Stats
 Mean Speed(Average) :
 24 MPH

 10 MPH Pace Speed :
 21-30 MPH

 Number in Pace :
 1062

 Percent in Pace :
 66.9%

 Number of Vehicles > 25 MPH :
 745

 Percent of Vehicles > 25 MPH :
 47.0%

SAMMAT ENGINEERING SERVICES, LLC

1515 RISING RIDGE ROAD MOUNT AIRY, MD 21771

www.sammateng.com

300 Block of Rock Creek Church RD NW SWB Volume

Start	Sun	10-Nov-13	Mon	11-Nov-13	Tue	12-Nov-13	Daily Av	/erage
Time	A.M.	P.M.	A.M.	P.M.	A.M.	P.M.	A.M.	P.M.
12:00	*	*	5	35	*	*	5	35
12:15	*	*	8	24	*	*	8	24
12:30	*	*	6	23	*	*	6	23
12:45	*	*	4	26	*	*	4	26
01:00	*	*	1	22	*	*	1	22
01:15	*	*	2	24	*	*	2	24
01:30	*	*	3	18	*	*	3	18
01:45	*	*	3	25	*	*	3	2
02:00	*	*	5	26	*	*	5	20
02:15	*	*	4	17	*	*	4	1:
02:30	*	*	4	31	*	*	4	3
02:45	*	*	0	32	*	*	0	32
03:00	*	*	3	27	*	*	3	2
03:15	*	*	2	31	*	*	2	3
03:30	*	*	1	27	*	*	1	2
03:45	*	*	2	42	*	*	2	4
04:00	*	*	0	20	*	*	0	20
04:00	*	*	4	31	*	*	4	3
04:13	*	*		32	*	*))
04:30	*	*	4 5	33	*	*	4 5	32 33
04:45	*	*			*	*		3:
05:00	*	*	3	26	*	*	3	26
05:15	*	*	8	32	*	*	8	32
05:30	*	*	6	24	*	*	6	24
05:45	*	*	8	19	*	*	8	19
06:00	*	*	11	36	*	*	11	36
06:15			9	26			9	26
06:30	*	*	14 13	27	*	*	14 13	27
06:45	*		13	19			13	19
07:00	*	*	23	16	*	*	23	16
07:15	*	*	18	23	*	*	18	2:
07:30	*	*	29	22	*	*	29	2
07:45	*	*	21	20	*	*	21	20
08:00	*	*	27	14	*	*	27	14
08:15	*	*	32	15	*	*	32	1:
08:30	*	*	21	10	*	*	21	10
08:45	*	*	23	13	*	*	23	1.
09:00	*	*	16	5	*	*	16 20	
09:15	*	*	20	16	*	*	20	16
09:30	*	*	20 23	15	*	*	20 23	1.
09:45	*	*	23	11	*	*	23	1
10:00	*	*	20	16	*	*	20	1
10:15	*	10	20 23	*	*	*	20 23	1
10:30	*	9	12	*	*	*	12	10
10:45	*	7	22	*	*	*	22	
11:00	*	4	21	*	*	*	21	
11:15	*	10	22	*	*	*	22	1
11:30	*	7	21	*	*	*	21	
11:45	*	14	23	*	*	*	23	1.
Total	0	61	575	951	0	0	575	1012
Combined								
Total	6	1	15	26	C)	1587	
Peak		11:00	07:30	03:00			07:30	03:00
Vol.		35	109	127			109	12
P.H.F.		0.625	0.852	_ 0.756			0.852	0.756
г.п.г.		0.023	0.032	0.730			0.032	0./30

Accident Summary Report (R-8)

Time Period Covered: Fi	rom 01/01/201	0 To 12/31	/2012 Prepar	ed By:	Rahul Jain	Prepared Da	te: 9	/15/2013
Total Number of Accident:		2	Collision Type	#ACC	° %	Collision Type	#ACC	9
Total Number of Fatalities:		0	Right Angle:	0	0.0%	Fixed Object:	0	0.0%
Total Number of Injuries:		0	Left Turn:	0	0.0%	Ran Off Road:	0	0.0%
Total Number of Disabling Ir	njuries:	0	Right Turn:	0	0.0%	Ped. Involved:	0	0.0%
Total Number of NonDisablin	ng Injuries:	0	Rear End:	0	0.0%	Backing:	1	50.0%
Total Number of Pedestrians	s Involved:	0	Side Swiped:	0	0.0%	Non Collision:	0	0.0%
Total Number of Bicycles Inv	volved:	0	Head On:	0	0.0%	Under/Over Ride:	0	0.0%
Total Number of Motorcycles	s Involved:	0	Parked:	1	50.0% l	Inspecified:	0	0.0%
Time of Day	#ACC	%			Day o fweek	#AC	C	9/
07:30 ~ 09:30:	0	0.0%			Sunday:	0		0.0%
09:30 ~ 11:30:	0	0.0%			Monday:	1		50.0%
11:30 ~ 13:30:	0	0.0%			Tuesday:	0		0.0%
13:30 ~ 16:00:	0	0.0%			Wednesday:	0		0.0%
16:00 ~18:30:	1	50.0%			Thursday:	0		0.0%
18:30 ~ 07:30:	1	50.0%			Friday:	0		0.0%
Unspecified:	0	0.0%			Saturday:	1		50.0%
Weather Condition	#ACC	%			Surface Condition	#AC	c	%
Clear:	2	100.0%			Dry:	2		100.0%
Rain:	0	0.0%			Wet:	0		0.0%
Snow:	0	0.0%			Snow/Ice:	0		0.0%
Sleet/Hail:	0	0.0%			Slush:	0		0.0%
Fog/Mist:	0	0.0%			Water/Sand:	0		0.0%
Crosswind/Blowing Sand:	0	0.0%			Repairing:	0		0.0%
Unspecified:	0	0.0%			Unspecified:	0		0.0%
Type of Vehicle	#VEH	%			Accident Severity	Type #AC	c	%
Passenger Car:	7	100.0%			Fatal Collision:	0	_	0.0%
Bus:	0	0.0%			Injury Collision:	0		0.0%
Truck:	0	0.0%			PDO Collision:	2		100.0%
Taxi:	0	0.0%			. 20 00			
Minivan:	0	0.0%			Light Condition	#AC	C	%
Police/Emergency Vehicle:	0	0.0%			Daylight:	1		50.0%
Motorcycle/Moped:	0	0.0%			Dawn/Dusk:	0		0.0%
Bicycle:	0	0.0%			Dark(Lighted):	1		50.0%
Fixed Object:	0	0.0%			Dark(Not Lighted):	0		0.0%
Unspecified:	0	0.0%			Dark(Unknown Ligh	ting): 0		0.0%
	· ·	0.070			Unspecified:	0		0.0%
Contributing Factor	#VEH	%			Pedestrian Actions	s #AC	С	%
Driver: Speed:	0	0.0%			In Crosswalk with S	ignal: 0		0.0%
Driver: Alcohol/Drug:	1	14.3%			In Crosswalk agains	st Signal: 0		0.0%
Driver: Electronic Device:	0	0.0%			In Crosswalk no Sig	ınal: 0		0.0%
Driver: Others:	1	14.3%			In Unmarked Cross	walk: 0		0.0%
Vehicle:	0	0.0%			Not in Crosswalk:	0		0.0%
Roadway:	0	0.0%			From Between Park	ed Cars: 0		0.0%
Unspecified:	5	71.4%			Unspecified:	0		0.0%

¹ Records are not approved as of 9/15/2013 12:27:05 PM